Download and install on a Windows machine. flash_download_tool_3.9.7_2.zip

Download the following test firmware. LED_Test.bin

Connect Programmer to unlockswitch.

Connect USB Cable to Computer and Programmer.

While Pushing and Holding the STRAP button. Push and release the CHIP_PU button. Now release the STRAP Button.

A new com port should appear.

Launch the application flash_download_tool_3.9.7.exe



Make setting are the same as image and the hit OK.



You should see the following screen. Add the LED_Test.bin and make sure the rest of the setting are the same.



Now find the COM port that was added.



Press the START button to begin program download.



Downloading



Finished Downloading

Push and release the CHIP_PU button. The LEDs on the unlockswitch should turn on and off sequentially. Green, Blue, Red, Green, Blue, Red……